

ASSEMBLY INSTRUCTIONS

CROWNMARK B4610/B4620-1 DRESSER


(BOX 1)

BOX OF DRESSER

NO	ITEM	QTY
A	DRESSER	1 pc
В	BUN FOOT	4 pcs
С	BOTTOM SUPPORT	1 pc



NO	ITEM	QTY
1	JCBC M6 x 50mm	4 PCS
2	Spring Washer 1/4" Rbw	4 PCS
3	Flat Washer 1/4"ID x 19mmOD Blk	4 PCS
4	ALLEN KEY m4x65mm Blk	1 pc



NOTE: MUST TIGHTEN SCREWS PERIODICALLY WITH USE SCREW WILL BECOME LOOSE CHECK TIGHTNESS OF ALL SCREW EVERY 6-8 WEEKS.