


1. Make sure you have the following parts:



**A Phillips Head Screwdriver
Is Needed For Assembly**

(4) Legs




(4) 2" Screws




(1) Placement Template




1. Working on a clean surface, turn the unit on its back with the unit base facing your work area.
2. Align placement template with edges of unit and place leg in the middle of hole cut out.
3. Attach (4) legs using (1) 2" screw per leg in holes provided.
4. Repeat the above procedures for the remaining legs.
5. Turn the unit upright and place the unit in desired location.




DWG# 93112
Date: 8/4/20
Rev: 8/25/20 ECO# 35515

1. Asegúrese de tener la siguientes partes:



Se necesita un destornillador
Phillips para el montaje

(4) Patas de plástico




(4) Tornillos de 2"




(1) Plantilla de colocación



1. Trabajando sobre una superficie limpia, coloque la unidad boca arriba con la base de la unidad mirando hacia su área de trabajo.
2. Alinee la plantilla de colocación con los bordes de la unidad y coloque la pata en el medio del agujero cortado.
3. Fije (4) patas usando (1) tornillo de 2" por pata en los orificios provistos.
4. Repita los procedimientos anteriores para las piernas restantes.
5. Coloque la unidad en posición vertical y colóquela en la ubicación deseada.




DWG# 93112
Date: 8/4/20
Rev: 8/25/20 ECO# 35515