ASSEMBLY INSTRUCTIONS

Do not tighten screws until completely assembled

20 not ingition out of a man compressor, accompany			
A	В	С	D
M6*15MM			
12PCS	12PCS	12PCS	1PCS
	D B C B C		