2848

ASSEMBLY INSTRUCTION




MADE IN CHINA

Do not tighten screws untill completely Assembled

STEP(1)	STEP (2)	STEP (3)
2 B B H	E D A H	
STEP (4)	STEP (5)	STEP (6)
	C D H B D B B B B B B B B B B B B B B B B	
STEP (7)	STEP (8)	
6 8 7		

PARTS LIST





HARDWARE LIST

NO.	Delineation	QTY	NO.		Delineation	QTY
A	Bolt Ø4"*2"	8pcs	F	0	Washer 01 ** *1 **	10pcs
В	Bolt Ø4"*14"	16pcs	G		Angle Iron	4pcs
С	Bolt Ø4"*12"	8pcs	Н		Allen Wrench	1pc
D	6 Lock Washer 01"	32pcs	I	M	Draw-hand	1pc
Е	① Washer Ø4"*5"	22pcs	J	Chanten	Bolt Ø ⁵ 32"* ⁷ 8"	1pc

ASSEMBLY INSTRUCTION 2848S-24 OAKLY COUNTER HEIGHT CHAIR




Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts which may come loose inside the carton during shipment.

Identify and count all parts.

NOTE: ASSEMBLE THE CHAIR ON A FLAT & SOFT SURFACE. DO NOT TIGHTEN ALL THE SCREWS UNTIL THE CHAIR HAS BEEN PUT A FLAT /HARD SURFACE ADJUST & LEVEL ALL THE LEGS SO THAT THEY DO NOT WOBBLE. ONCE ADJUSTED THEN TIGHTEN ALL THE SCREWS.


PARTS LIST		
NO	DESCRIPTION	QTY
1	CHAIR FRAME BACK	1
2	BOX SEAT	1
3	FRONT LEG (L & R)	2
4	SIDE STRETCHER (L & R)	2
5	FRONT STRETCHER	1

HARDWARE LIST			
NO	DESCRIPTION	QTY	
Α	JCBC SCREW M6 x 80MM WITH LOCK WASHER & WASHER	4	
В	JCBC SCREW M6 x 60MM WITH LOCK WASHER & WASHER	4	
С	JCBC SCREW M6 x 35MM WITH LOCK WASHER & WASHER	2	
D	ALLEN KEY M4	1	
Е	PAN HEAD #8 x 32MM	6	



NOTE: TO ENSURE CHAIR DURABLE AND LONG LASTING, PLEASE CHECK ENTIRE CHAIR PART WHETHER IT'S IN SAFE AND ORDINARY CONDITIONS.

MARKING





ASSEMBLY INSTRUCTION COUNTER HEIGHT TABLE 2848T-6060-TOP / 2848T-6060-LEG

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts which may have come loose inside the carton during shipment. Identify and count all parts and compare with the Parts List below.

**Assemble the table on flat, soft surface such as carpet or cloth to prevent scratching table finish. Read all the instruction and study the drawings carefully before starting the assemble process.

Caution: Wipe up spills as soon as possible. Please wipe with dry rag right away.

PARTS LIST

NO	DESCRIPTION	QTY
1	TABLE TOP	1 PC
2	TABLE LEG	4 PCS
3	TABLE BASE	1 PC
4	SIDE PANEL	4 PCS
5	CENTER PANEL	2 PCS
6	SHELF PANEL	2 PCS
7	LAZY SUSAN	1 PC


HARDWARE LIST

NO	DESCRIPTION	QTY
Α	JCBB SCREW (NYLOK) 5/16" x 2 1/2" WITH LOCK WASHER & WASHER	8
В	ALLEN KEY M4	1




Part (2) x 4pcs

Part (3) x 1pc



STEP 2

Part (4) x 2pcs





STEP 4 STEP 3 Part (5) x 1pc Part 6 x 1pc 6 STEP 5 STEP 6 Part 4 x 2pcs Part (5) x 1pc (5) 4

Page 2 of 3



